

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 13


Township: 8 North

Range: 1 West

Corner ID: ClCr Y-13

Monument Description & Remarks: 3/4" Iron Pipe 4" above ground. Survey Sign 4ft above ground at pt. B

References On File: Matthew L. Cooper survey, Instrument Number 2005011737 (2004), on file in Recorder Office cabinet S, envelope 285



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 30th day of June 2008.

Kevin P. Enright



Administered by the Monroe County Surveyor Review Board

Date: 7-6-2008

Index:	N-25	Corner:	Poss. S.C.	LAND CORNER RECORD				State of Indiana Hoosier National Forest	
Twnshp:	7N	Range:	1W	Section:	13/24	2 nd P.M.	County	Monroe	

EXISTING SURVEYS

Original Government Survey

Year Surveyed:				By:			
Original Monument:							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Where Filed or Recorded:							
Book:	Page:	Date:					
Monument Set:							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

Original Survey Evidence Found

Date of Search:				By:			
Monument Found:							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration Found

Year Searched:	9/17/04	By:	B.Stone				
Monument Found	¾" diameter galvanized pipe standing 4" above ground						
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The pipe is located on a steep west slope approximately 250 feet uphill from the waters edge of Lake Monroe. A 4 foot tall metal U-shaped post stands 0.5 feet west. Orange flagging is tied to the pipe and post which may have been set by the Army Corp of Engineers when they acquired land for Lake Monroe	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.	
	

Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.											
Section: 24	No blazes, tags or paint is on these trees: <table> <tr> <td>Maple</td> <td>Beech</td> </tr> <tr> <td>10"</td> <td>30"</td> </tr> <tr> <td>N 71°E</td> <td>S 29°W</td> </tr> <tr> <td>5.2 Ft.</td> <td>15.6 Ft.</td> </tr> </table>				Maple	Beech	10"	30"	N 71°E	S 29°W	5.2 Ft.	15.6 Ft.
	Maple	Beech										
	10"	30"										
	N 71°E	S 29°W										
	5.2 Ft.	15.6 Ft.										
Corner Recordation:		Certificate Prepared:										
Filed and Recorded in County records:		Date:										
Book:		Page:										
Geodetic Coordinates:		Lat./N.	Long./E.									
Edited By:	Robert J. Stone	Date Created:	11/23/04									

Index No. N-25
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)


R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1W 2nd Mer. N.F. HOOSIER County MONROE State IND
SECTION Corner common to sections 13 24 and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1867</u> By _____	Year of search _____ By _____
Where filed or recorded <u>MON CO. ENG OFFICE</u>	
Monument _____ (Original, concrete post, iron rod, etc.)	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species <u>W. OAK</u> <u>Beech</u> <u>W. OAK</u>	
Diameter <u>20"</u> <u>5"</u> <u>10"</u>	
Bearing <u>N 65 E</u> <u>S 8 W</u> <u>S 17.5 W</u>	
Distance <u>4 LKS</u> <u>4 1/2 LKS</u> <u>23 1/2 LKS</u>	

T7NRIW T7NRIE



Sketch

O Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____